


A600 Series TriTask Aircraft Jacks

Parts List

July 01 2017



32 Complete Pump Assembly (not shown)

33 Hydraulic Repair Kit (not shown)

Parts List

A622, A627 and A634 TriTask Aircraft Jacks

No.	Part No.	Description	#/Unit
1	A622-A	Frame Weldment (for A622) (not available)	1
1	A627-A	Frame Weldment (for A627) (not available)	1
1	A634-A	Frame Weldment (for A634) (not available)	1
2	A400-B	Steady Knob	2
3	5400	Teflon Washer	1
4	6235	Reservoir Fill Bolt	1
5	EX-16	Extension Handle	1
6	6700	Snap Rings	5
7	7430	Caster Spring	3
8	7215	Caster	3
9	CWAC-A	Caster Assembly	3
10	A400-10	Cylinder Retaining Pin	1
11	6180	Pull Knob	1
12	A400-L	Lock Pin Housing	1
13	7420	Spring	1
14	9708	Lock Pin	1
15	A400-LPA	Lock Pin Assembly	1
16	A622-15	Hydraulic Piston Rod (for A622)	1
16	A627-15	Hydraulic Piston (for A627)	1
16	A634-15	Hydraulic Piston (for A634)	1
16A	D100-8	Hydraulic Piston Stop	1
17	D100-6	Gland Nut	1
17A	5304	Piston Wiper Ring (1")	1
18	5031	Hydraulic Square Seal	1
19	D100-7	Seal Spacer	1
20	CW-A622	Cylinder Weldment (only) (for A622)	1
20	CW-A627	Cylinder Weldment (only) (for A627)	1
20	CW-A634	Cylinder Weldment (only) (for A634)	1
21	CA-A622H	Hydraulic Cylinder Assembly w/Hose (for A622)	1
21	CA-A627H	Hydraulic Cylinder Assembly w/Hose (for A627)	1
21	CA-A634H	Hydraulic Cylinder Assembly w/Hose (for A634)	1
22	AT62222	Inner Slide Tube (for A622) (includes #31)	1
22	AT62727	Inner Slide Tube (for A627) (includes #31)	1
22	AT63434	Inner Slide Tube (for A634) (includes #31)	1
23	MH-18	Hose Assembly	1
24	8020	A/C Inspection Hole Sticker	1
25	8120	6,000# Capacity Sticker	1
26	8005	MHC Corporate Decal	1
27	8050	Oil Level Sticker	1
28	8051	Oil Instruction Sticker	1
29	8040	Product Service Sticker	1
30	7890	Brass Tag with Rivets	1
31	8022B	AT622nn Caution Label (for A622)	1
31	8019B	AT627nn Caution Label (for A627)	1
31	8023B	AT634nn Caution Label (for A634)	1
32	PAF45180P	Complete Pump Assembly w/EX-16 (for A622 or A627) (not shown)	1
32	PAF60180P	Complete Pump Assembly w/EX-16 (for A634 only) (not shown)	1
33	K-150B	Hydraulic Repair Kit (not shown) (includes pump repair kit items plus 5031 above)	1
34	AT-JPR1	Jacking Point Receiver	1